

5/015/055

RECEIVED

JUN 07 1993

Moab District  
San Rafael Resource Area  
900 North 700 East  
Price, Utah 84501

DIVISION OF  
OIL GAS & MINING

3809  
UTU-69858  
(U-067)

Mr. Winston Stocks  
Mr. Clayton Stocks  
P.O. Box 492  
Moab, Utah 84532

JUN 3 1993

Dear Messrs. Stocks:

We completed an inspection of work done on your ALA #1-15 mining claim group and the reclamation work completed to date is insufficient. Large boulders of gypsum are lying at the surface such that the area has not been returned to its original state. These boulders need to be buried or removed, at least in those areas where there was not an outcropping of gypsum previously in existence.

We would like to set up a field examination to discuss the degree and location of any further reclamation work at your earliest convenience. Please contact Neil Simmons of my staff at 801-637-4584 to set up a meeting.

Sincerely,

/S/ NEIL A. SIMMONS

Area Manager

cc: Holland Shepherd, UDOGM  
Bryant Anderson, Emery County

Acting

NSimmons:ks:4/29/93  
STOCKS.LTR